

Operating instruction in accordance with § 14 GefStoffV,

Building:	Workplace:
Operation/Department:	Activity:
Date/released:	Entry date:

**HAZARDOUS SUBSTANCE / PRODUCT DESIGNATION****EdgeMet Solution A****Contains:** Nickel dichloride**DANGERS FOR HUMANS AND ENVIRONMENT****Toxic****Dangerous for the environment**

R 20/22: Also harmful by inhalation and if swallowed. R 48/23: Also toxic - danger of serious damage to health by prolonged exposure through inhalation. R 42/43: May cause sensitisation by inhalation and skin contact. R 49: May cause cancer by inhalation. R 51/53: Toxic to aquatic organisms, may cause long-term adverse effects in the aquatic environment. R 61: May cause harm to the unborn child. R 68: Also possible risk of irreversible effects.

Reactions with strong alkalies and oxidizing agents.

PROTECTIVE MEASURES, RULES OF CONDUCT**Hygiene measures:****Respiratory protection:****Hand protection:****Eye protection:****Skin protection:**

Do not eat, drink, smoke or take drugs at work. Remove contaminated soaked clothing immediately and dispose of safely. Use barrier skin cream. After worktime and before work breaks the affected skin areas must be thoroughly cleaned.

Breathing apparatus in the event of high concentrations.

Short term: filter apparatus, filter P3.

Butyl rubber, >120 min (EN 374).

Safety glasses.

Light protective clothing of plastic material.

BEHAVIOR IN THE CASE OF A DANGERTelefon: **Suitable extinguishing media:****Environmental precautions:****Methods for cleaning up:**

Product itself is non-combustible. Fire extinguishing method of surrounding areas must be considered.

Fire residues and contaminated firefighting water must be disposed of in accordance within the local regulations. Wear full protective suit. Use self-contained breathing apparatus.

Ensure adequate ventilation. Use personal protective equipment (protective gloves, safety glasses, protective clothing).

Do not discharge into the drains/surface waters/groundwater. Prevent spread over a wide area (e.g. by containment or oil barriers).

Take up with absorbent material (e.g. general-purpose binder). Dispose of absorbed material in accordance within the regulations.

FIRST AID MEASURESTelefon: **General information:****Inhalation:****Skin contact:****Eye contact:****Ingestion:**

Remove contaminated soaked clothing immediately and dispose of safely.

Ensure supply of fresh air.

In case of contact with skin wash off immediately with soap and water.

Consult a doctor if skin irritation persists.

In case of contact with eyes rinse thoroughly with plenty of water and seek medical advice.

Rinse out mouth and give plenty of water to drink.

DISPOSAL CONSIDERATIONSTelefon:

Dispose of as hazardous waste.

Packaging that cannot be cleaned should be disposed of as for product.

Waste no. (recommended):060313*